

Project: A	Alaska Copper V	<u> Vorks</u>			Inspec	tion Date: 3/12/19
Project No.: 1	8ACW1				Т	echnician: David DuBois
System Perfor	mance:					
Was system run	ning during the i	nspection?	☐ Yes	⊠ No		
Flow Rates (gpn	n)	Influent	90	Effluent _	140	The flows should be ~155 gpm
Bag Filter #1 Pre	essures (psi)	Influent _	15	Effluent _	12	The bag filters should be replaced
Bag Filter #2 Pre	essures (psi)	Influent _	15	Effluent _	12	if differential pressure > 8 psi
Carbon Filter Pr	essures (Lead)	Influent _	10	Effluent _	6	The carbon filters should be backflushed if differential
Carbon Filter Pr	essures (Lag)	Influent _	4	Effluent _	0	pressure > 8 psi
Were the bag fil	lters replaced?	□ Yes 🗵	No			
Was the carbon	backflushed?	□ Yes 🗵	No			

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	☑ Yes ☐ No	
Flow Meters Inspected	⊠ Yes □ No	
Level Sensor Cleaning/Inspection	⊠ Yes □ No	
Inspect System Plumbing	⊠ Yes □ No	
Pumps Inspected	ĭ Yes ☐ No	
General Housekeeping	☑ Yes ☐ No	
Chemistry Level	☑ Yes ☐ No	1.75 drums onsite
Safety Materials Inspected	☑ Yes ☐ No	
pH Probe Inspection/Calibration	☑ Yes ☐ No	Inline probe verified within 0.05



Water Sampling:					
Were water samples	taken?	☐ Yes	s ⊠ No		
Raw water:	pН	6.56	Turbidity _	17	_NTU
Bag Filter Influent	рН	7.34	Turbidity _	17	NTU
Bag Filter Effluent	pН	7.21	Turbidity _	13	NTU
Carbon Filter Influent	рН	7.75	Turbidity _	6	_NTU
Carbon Filter Effluent	рН	8.03	Turbidity _	4	_NTU
Monthly Tasks:					
Were samples submit	ted to	Analytical [*]	?□Yes⊠No)	
Analytical Lab:		***************************************			
Was Walchem data d	ownloa	ided?	☐ Yes ☒ No)	
Were the tank sludge	levels	checked?	☐ Yes 図 No)	
Sludge Depth (inches) :				
Decant Tank:	0				
Treatment tank:	0				
Backflush tank:	0				
Main lift station:	-				
North lift station:					
South lift station:	-				
Additional Comment	s, Reco	mmendat	ions and Syste	m Ups	ets:

David DuBois Project Lead Tech 3/12/19
Technician Title Date

Submit

Page 2 of 2